



DATE 8/26/82

**SSC Service Bulletin**

no. 82-270

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS  
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: MA-330'S SHIPPED BETWEEN JULY 1982 AND AUGUST 1982

SYMPTOM: EXCESSIVE BASE TONE IN TRANSMIT AUDIO

CURE:

Change C4 and C8 from .47 $\mu$ F to .001 $\mu$ F (1518-0102-002).

TECHNICAL SERVICE DEPARTMENT  
REGENCY COMMUNICATIONS, INC.

